SEMO, SEMOpx Known Issues Report 22 February 2019

SEMOpx								
ID	Name	Description	Impact to Market Participants	Status	Resolution Date	Proposed Release Date	Release Version	
92601	ETS Auction Results Message	Message log is not retaining the message indicating availability of	No material impact to SEMOpx Members. Members can view all auction results. Members will need to look at auction results reports/screens to determine availability of auction results, as opposed to reviewing the message log.	Unplanned	No Confirmed Delivery date			

Balancing Market						
ID	Name	Description	Impact to Market Participants	Status	Resolution Date	Proposed Release Date Release Version
5737			, , , , , , , , , , , , , , , , , , , ,	Planned Release Date	In Day 1 plus scope, Quarter 1 release Resolution: Software update from vendor	March 2019
5831	•	Dispatch Instructions which are cancelled with a 'Not Accepted' status are being processed in pricing	Incorrect OBOA values, resulting in impact to Imbalance Price.		In Day 1 plus scope, Quarter 1 release Resolution: Software update from vendor	March 2019
5785			Incorrect PBOA values, resulting in impact to Imbalance Price		In Day 1 plus scope, Quarter 1 release Resolution: Software update from vendor	March 2019
5497	VTOD Soak Times	SOAK HOT QUANTITY values are incorrect. The values shown are the SOAK HOT QUANTITY values. Please note: the integrity of the VTOD set is unaffected. This is	This leads to confusion for MPs as they cannot view the accurate Soak WARM QUANTITY values. The SO and MO approve the correct values, and those are used in the Scheduling & Dispatch process.	In Analysis	In Day 1 plus scope, target to include in Rel C. Note this is not yet confirmed. Resolution: Software update from vendor	
5817	Initial conditions being incorrectly reset in some circumstances	Initial conditions being incorrectly reset in some circumstances	Incorrect QBOA values, resulting in impact to Imbalance Price	In Analysis	In Day 1 plus scope, target to include in Rel C. Note this is not yet confirmed. Resolution: Software update from vendor	
5641	-	MW QTY values in REPT_078, _079, _080 are not being calculated correctly.	Participants cannot rely on these data until the issue is resolved. Participants should use alternate means to formulate these totals. These data are available at the individual portfolio (unit) level in the ETS Market Results files published D+1.	In Analysis	In Day 1 plus scope, target to include in Rel C. Note this is not yet confirmed. Resolution: Software update from vendor	
5796	IREPT 042	The Forecast Imbalance Report is not calculating the some of the data within the reports correctly.	The Net Interconnector Schedule value is incorrectly reporting as 0 when both interconnectors are on full export. The data for the Moyle Interconnector are sometimes not contained within the calculated and reported value for the Net Interconnector Schedule attribute.	In Analysis	In Day 1 plus scope, target to include in Rel C. Note this is not yet confirmed. Resolution: Software update from vendor	
5844 (PNs)	IRFPT 042		The PNS are currently being calculated incorrectly. The report presents inaccurate information.	In Analysis	In Day 1 plus scope, target to include in Rel C. Note this is not yet confirmed. Resolution: Software update from vendor	
5913 (TSO Demand Forecast)	IREPI (147	The Forecast Imbalance Report is not calculating the some of the	The TSO Demand Forecast value is inaccurate as it reads from the all island values and reports inaccurate figures. The report corrects itself and is accurate leading up to the gate closure	In Analysis	In Day 1 plus scope, target to include in Rel C. Note this is not yet confirmed. Resolution: Software update from vendor	
5841	Instructions Report	Instruction. However this conflicts with the XSD schema for the	Market Participants Market tools may fail to pull this report where a dispatch instruction contains a null dispatch instruction. Report is now available in all cases were before the report was available intermittently.	In Analysis	TBC Resolution: Software update from vendor CR currently in review	
5794	TREPT 030 REPT 103	, , , , , , , , , , , , , , , , , , , ,	Participant unable to acquire these data until this issue is addressed		TBC Resolution: Software update from vendor CR currently in review	
SEMO_WEB.001	SEMO and SEMOpx ongoing	The SEMO and SEMOpx website currently has issues with the dynamic reporting, report retention and ongoing manual workaround to publish reports	This impact report availability to participants as well as use of dynamic reporting to provide an accurate representation of the static reports. All reports are available in the static section and manual workaround are carried out on a daily basis to ensure reports are not missed	In Analysis	TBC Resolution: Software update from vendor	
SEMO_WEB_002	•	historical reports	MPS are unable to download historical reports from the SEMO and SEMOpx website. A CR has been raised with the website vendor to make these files available	In Analysis	TBC Resolution: Software update from vendor TBC	
108598	•	The Imbalance price is using the market backup price for multiple periods at a time during the night.	Participants are receiving the market backup price for multiple periods at a time.		Resolution: Software update from vendor	
82044	The Interconnector NTC report	however is currently showing the TTC (Total Transfer Capacity) values. This is due to a configuration change requested by National	Report is designed to show NTC (Net Transfer Capacity) values however is currently showing the TTC (Total Transfer Capacity) values. This is due to a configuration change requested by National Grid prior to go-live	In Analysis	TBC Resolution: SEMO are carrying out an impact assessment as this impacts multiple IT systems and also has a knock on impact for other processes.	
5845	REPT_022: Initial Interconnector Flows and Residual Capacity	This report is appearing EMPTY in the MPI and website.	There are no data available in the report.	,	TBC Resolution: Software update from vendor CR currently in review	
5806	DESY Pumped Storage instructions are not processing correctly	HIESY PHIMAER STORAGE INSTRUCTIONS ARE NOT ARCCESSING CORRECTIV	Incorrect QBOA values, resulting in impact to Imbalance Price. A workaround has been put in place for this issue.		TBC Resolution: Software update from vendor	
105605	List of Registered Units' report	Report currently creates multiple records for each registered unit, each one with a different trading site. It will create these multiple records for each trading site which is assigned to the unit's participant. It is also creating multiple (duplicate) records with a N/A trading site	Report contains duplicate records		TBC Resolution: Software update from vendor	
109895		Duplicate entries are appearing in the Dynamic report for Daily meter data.	Data is currently duplicated on the following dates in the dynamic meter data report on the website. 17th + 27th Nov 7th Dec has 3 line entry per timestamp 13th Dec 11th + 19th Jan.	In Analysis	TBC Resolution: Software update from vendor	
110321	Incremental & Decremental Price quantity pairs	When a participant submits 9 Price Quantity Pairs for Incremental and Decremental costs curves the sequences do not see the prices as monotonically increasing and then defaults them to zero. This is a defect and has knock on impacts on the scheduling of LTS, RTC and RTD	As a workaround participants are requested to not submit 9 PQ pairs when submitting Commercial Offer Data.		TBC Resolution: Software update from vendor	
5329	Reports missing 1st ISP of Trade Day	REPT_078: Aggregated Contract Quantities for Generation REPT_079: Aggregated Contract Quantities for Demand	The MPs will not be able to source data for the first ISP of a trade date from this report until the issue is remedied. These data can be sourced elsewhere. They are available in the ETS Market Results published on the SEMOpx website, D+1.	In the process of submission to the RA's for approval	TBC Resolution: Software update from vendor	
5587	SEMO Website	REPT_027 (Four Day Rolling Wind Forecast) and REPT_013 (Daily	No material impact to Market Participants or General Public as these reports are now being uploaded manually to the SEMO website.	submission to the	TBC Resolution: Software update from vendor	
5603	INC and DEC Curves	Currently the report cumulatively adds each MW quantity to the last MW quantity rather then the difference. This results in erroneous MW values in the report.	9	In the process of submission to the RA's for approval	TBC Resolution: Software update from vendor	
5845	REPT_022 Showing Empty	The Initial Interconnector Flows and Residual Capacity Report (REPT_022) is produced EMPTY on the MPI, and subsequently to the SEMO website. This is an error with the vendor design that causes the report to fail when no SO Trades are available in the system.	·	In the process of submission to the	TBC Resolution: Software update from vendor	

5644	REPT_011 Duplicate Entries	Entries for each COD offer type (Simple/Complex) leading to the duplicate entries in Daily Technical Offer Data Report	Impacting units with both Simple and Complex COD submissions. Participants to continue to use report as normal	Unplanned	No Confirmed Delivery date
5740	Annual CLAF Report not produced and available via MPI	REPT_023: Annual CLAF Report is not produced and available via the MPI.	The Annual CLAF is published to the SEMO website in XLS format. The production of the XML version (specified as REPT_023) is subject to a software update from the vendor. Market Participants and General Public audiences can download the data from the SEMO website, albeit in a different format.	Unplanned	No Confirmed Delivery date
5751	REPT_014: Daily Demand ControlData	IREPT 014 is producing incorrect demand control values	The data in the report are incorrect and not available from other sources	Unplanned	No Confirmed Delivery date
5812	REPT_068 UOM error	the "Dispatch Quantity" field as MW for P/S units when in pumping	MPs will observe incorrect values for pumping mode MWh values in this report until remedied. Settlement is unaffected as those calculations use metered generation.	Unplanned	No Confirmed Delivery date
102081	REPT_006: Daily DI Report	Intracards and does not attact the instruction profiling process	For P/S units, the Market Participant will need to ignore the duplicate entry until resolved.	Unplanned	No Confirmed Delivery date
5756	REPT_011	Various flags incorrect in REPT_011 (Daily Technical Offer Data Report) – PUMP_STORAGE FLAG, Fuel Type for Pumped Storage Units (linked to PUMP_STORAGE FLAG issue), Firm Access Quantity defaulting to zero for all units (should be Trading Site FAQ)	Participants to continue to use report as normal	Unplanned	No Confirmed Delivery date
5870	REPT_081 hourly Anonymized INC and DEC Curves	REPT_081 can contain records for a full day rather then on a 30 minutes basis as per design	Report can publish inaccurate data	Unplanned	No Confirmed Delivery date
5195	Report display	HTML report is displayed in UTC rather than always in local time.	This issue affects 39 reports. This is a display issue only, as the values and corresponding time interval are correct.	Unplanned	No Confirmed Delivery date

SEMO Settlement							
	Nama	Description	Impact to Market Participants	Status	Resolution Date	Dranged Balance Date	Release Version
ID	Name	Description	Impact to Market Participants	Status		Proposed Release Date	Release version
5931	ISEM_OUI and CSB_CIMB incorrectly been charged to interconnectors	ICSB is not calculating the interconnectors CIMB incorrectly	No impact to market participants manual workaround is in place.	Closed	In Day 1 plus scope, Quarter 1 release Resolution: Software update from vendor	18th Feb 2019	
5883		Difference Payment Calculation sets final QDIFFTRACK to zero if there are no intraday trades - Supplier Unit	Difference payment Calculations are incorrect when a supplier unit has no intraday trades	Closed	In Day 1 plus scope, target to include in Rel C. Note this is not yet confirmed. Resolution: Software update from vendor	19th Feb 2019	
5657	Illnits registered as part of an	units which is registered as part of an Autoproducer site	lthis issue. We will retain the item on this list, but it has no	Planned Release Date	In Day 1 plus scope, Quarter 1 release Resolution: Software update from vendor	March 2019	
5808	laligned with the Trade and	FMOC is applying the trading day exchange rate of the last day of the month.	FMOC is applying the trading day exchange rate of the last day of the month.	In Analysis	In Day 1 plus scope, target to include in Rel C. Note this is not yet confirmed. Resolution: Software update from vendor		
5893	Incorrect IPQBOA values	BOAs were intermittently calculated incorrectly when QD was equal to the FPN with a BOA generated. Also where QD is similar to FPN yet large variances in QAO and QAB.	IPQBOA values were not correct. Temporary workaround is in place. Permanent solution to be provided by ABB	In Analysis	In Day 1 plus scope, target to include in Rel C. Note this is not yet confirmed. Resolution: Software update from vendor		
5886	being kent for 2 months	All Settlement reports produced in MMS currently only have a retention of 2 months in the MPI. They are then archived and not available through the front end	Settlement reports/documents/Statements unavailable to participants after 2 months through the MPI. Temporary workaround applied on the 21/01/2019 ensures that no further report will be removed from the MPI. Vendor is working on solution to republish all Settlement reports/documents/Statement to MPI	In Analysis	TBC Resolution: Software update from vendor		
5888	IMetered Ouantity for DSHs		Affecting settlement calculations for DSUs, resulting in non-zero undelivered quantities, which should be zero.	In Analysis	TBC Resolution: Software update from vendor		
5940	MPOP FPN Misalignment with	not aligned with the MM, including incorrect application of minute	Not applying the correct starting points for FPNs in relation to the calculation of fixed costs for the Period of Market Operation	In Analysis	TBC Resolution: Software update from vendor		
5944		CSB not receiving correct FPN curve from Balancing Market resulting in incorrect Start-Up status.	Incorrect or No Heat State being applied within CSB, therefore Start-Up costs not being included within the CFC calculation	In Analysis	TBC Resolution: Software update from vendor		
5910		MA is currently providing Startup Flag and Warmth State for Synchronize Dispatch Instructions that relates to CSU calculation	This affects CFC calculation	In Analysis	TBC Resolution: Software update from vendor		
5909	Inot heing calculated when first	System changes between Simple and Complex COD use when the Order of the first BOA does not equal 1.	This affects CFC calculation	In Analysis	TBC Resolution: Software update from vendor		
5314	IREPT OAR OAA	which it should not	Market participants and any third-party system providers should ignore the additional 1-second on the timestamp and consider the time to be exactly on the ISP interval.	Unplanned	No Confirmed Delivery date		
5322			The difference in time is very brief and has no material effect on the report quality.	Unplanned	No Confirmed Delivery date		
5339	IREPT 043	records do not sum correctly	Inconsistency between detailed and summary records within the same REPT_043. Research indicates this to be small amount relative to document totals.	Unplanned	No Confirmed Delivery date		
5772	Capacity Charges/Payments	CCC, CCP and CSOCDIFFP settlement for NI units not applying the Annual Capacity Exchange rate as per G.1.3.5 & G.1.3.6. Balancing market FX rate incorrect being applied.	CCC, CCP and CSOCDIFFP settlement for NI units not correct.	Unplanned	No Confirmed Delivery date		